Southern Vermont historical structure sampling.

Brattleboro Vermont

West Brattleboro apartments 1800?, 1837, 1850, 1868?, 1894 Historic structure sampled during repairs 07/2002 WBA Hemlock (60/66), spruce (2/6), oak (16/23) Cutting dates 1799? (1), 1835 (1), 1836 (8), 1837 (1) 1849 (3), 1867 (1), 1894 (1) Time-span of samples: 1499 – 1894 Contacts: Lyssa Papazian, Martha Radcliffe

Estes Organ House 1856

Samples from Jason Breen 2004 EOH Hemlock (1/_) Cutting dates 1855 (1) Time-span of samples: 1753 – 1855

Guilford Vermont

Christ Church 1817 (documents) repairs 1835 Historic meeting house sampled 08/2003 CCG Hemlock (/), white pine (1/), beech (/), oak (1/) Cutting dates 1815 (1),1816 (1), 1834 (3) Time-span of samples: 1680 - 1834 Contacts:George & Laura Lewis 802-254-4839

Gale Farm barn 1835, 17?? Barn, east Guilford. Posts, braces sampled 08/2003 Original structure with gunstock posts no cutting dates. GFB Hemlock, oak, beech, yellow birch, red pine (0/1) Cutting dates 1832 (2), 1833 (1) 1834 (2) Time-span of samples: 1668 - 1834 Contacts: Bernie & Brenda La Rock 1266 Coolidge Hwy, Guilford 802-254-4222

Gale Farm sugarhouse 1867 Sugar house frame sampled 08/2003 GSH Hemlock (9/9), cherry (0/3) Cutting dates 1866 (4) Time-span of samples: 1587 - 1866 Contacts:

Wolcott house 1784? Samples 08/2003WHG Hemlock (1/1), beech Cutting dates 1783 (1) Time-span of samples: 1701-1783 Contacts: Jeff Woodward <u>wdesign@sover.net</u> 802-257-5827 Evans Farm barn 1802, repairs 18_, 1913

Sampled 07/2001 Farmstead, Guilford. Samples from posts, braces, and rafters. Hemlock, ash, beech, oak. EFB Cutting dates 1798 (2), 1801 (4), 1802 (4), 1912 (1) Time-span of samples: 1547 - 1912 Contacts: Harry Evans 121 Weatherhead Hollow Rd, Guilford, 05301

Evans farm sugarhouse 1877

Samples from frame and siding boards. 07/2001 ESH Hemlock, ash (1/1) Cutting dates 1876 Time-span of samples: 1684 - 1876

Goodenough Farmstead 1788?

Historic farm, Guilford. Sampled 07/2003 GFH, GFB Beech, yellow birch, oak, hemlock, pine, cherry Cutting dates ---Time-span of samples: Contacts: Michael Weitzner Thistle Stone Works 802-254-9869

... *house* 1792 Hemlock (/), beech (/), yellow birch (/) LHA Cutting dates 1791 (2), 1835 (1) Time-span of samples: Contacts: Jason

Guilford Center meeting house 1788, 1835 (1837 documents) Historic meeting house sampled 07,11/2002 GCM White pine, hemlock, oak, beech(1), yellow birch(2), maple (1) Cutting dates 1787 (9), 1834 (3) Time-span of samples: 1453 - 1835 Contacts: Fred Humphrey

Guilford Center school 1797 (documents) Sampled 11/2002

Hemlock (2/4) GOS Cutting dates ---Time-span of samples: 1688 - 1780) Contacts: Fred Humphrey 802-257-7306

Ashworth farm 1855 (documents) Sampled 11/2002 AWF Hemlock (4/4), cherry (1/1) Cutting dates 1854 (2) Time-span of samples: 1634 - 1854 Contacts: Paul & Roger Barrett, Guilford Center Road

Breen house 2004

New construction, local hemlock Cutting dates ---Time-span of samples:

Thurber farm 2002 Post ends from Jason Breen Barn, new timber frame, local hemlock. TFB Cutting dates ---Time-span of samples: 1854-1999

Green River

Green River house 1835-7 Residence, Green River. Sampled during repairs 07/2003 GRH Hemlock, spruce, pine Cutting dates 1834 (4), 1835 (2), 1836 (1) Time-span of samples: 1568 - 1836 Contacts: Joan Seymour Box 2435, Guilford,05301 802-257-5771

Green River crib dam 1871 Historic crib mill dam. Sampled during repairs 07/2003 Hemlock (3/3) GRD Cutting dates 1870 (3) Time-span of samples: 1661 - 1870

Green River covered bridge 1870 (documents) Historic bridge. GRB Salvaged timber from repair. Spruce (1/1) Cutting dates ---Time-span of samples: 1710 - 1842

Marlboro Vermont

Marlboro Town House 1778 (documents) 1825 Historic structure, Marlboro center. Sampled 07,08/2003 Roof trusses, rafters. MTH Ash, spruce, white pine, beech Cutting dates 1777(4), 1823(1), 1824 (2), 1841 (1) Time-span of samples: 1591 - 1824 Contacts: Forrest Holzapfel, Box 66, Marlboro 05344 802-258-2568

Ames Hill house 1829?

Farmhouse, Marlboro. Sampled 07/2002 Floor joists, loose material. AHH Spruce, hemlock Cutting dates 1828 (1) 1856 (1) Time-span of samples: 1626 - 1828 Contacts:

77 house 1830? Nathaniel Whitney homestead Farmhouse, Marlboro. Sampled 07/2002 Floor joists. 77H Spruce Cutting dates 1829 (1) Time-span of samples: 1548 - 1829 Contacts: Kenwood Farm, Marlboro

Putney Vermont

Barton Farm 1819, 1848, 1864 Farm house, barn, sheds. Sampled 08/2003 Posts, floor and ceiling joists. BFB, BFH, BFS Hemlock, beech, Cutting dates 1810 (1),1818 (2), 1847 (3), 1863 (1) Time-span of samples: 1622 - 1863 Contacts: Josh Laughlin 78 Tavern Hill Rd, Putney 05346

Putney Road apartments (Mellen Store) 1839

Putney town, sampled after fire, 08/2003 Wall studs. PRA Hemlock Cutting dates 1838 (2) Time-span of samples: Contacts: Andrew Demasi 532 Aten Rd. Munsonville NH 05457

Hi Lo Biddey farm 1849

Material from , 2003 HLB Hemlock, white pine, red pine Cutting dates 1848 Time-span of samples: Contacts: Tim Ragle 71 Hi-Lo Biddy Rd. Putney 05346 802-387-2650

Dummerston area

Dummerston covered bridge 1872 (documents) Historic bridge over West River. Sampled 1998 Material from lattice truss. DCB, DBC, DBP Hemlock (/), spruce (/), oak (/) (many, oak trunnels) Cutting dates 1867 (1), 1868 (6), 1869 (5), 1870 (4) Time-span of samples: 1555 - 1870

Fair Winds Farm 1810?, 1828, 1838, 1880, 1922

Farm, U Dummerston Road. Barn, house, horse barn. Posts, rafters, joists, loose material. Sampled at various times. FWF-B,H, BBV. Hemlock, w pine. Cutting dates 1809, 1827, 1837, 1879, 1921 Time-span of samples: 1666 - 1921

Upper Dummerston school 1884 Residence, UD Road. Rafters, studs, sampled during repairs 08/2003 UDS Hemlock(12) Cutting date(s) 1884 (4) partial.

Margaret Everett Barn, Dummerston Center, 1788, 1857 Sampled 2014 East and west halves during demolition. Posts and roof timbers MEBE, MEBW White pine (4/4), oak (4/4), hemlock (1/3) Cutting dates 1787 (4), 185_ Time-span of samples 1661-1856 Contacts: Margaret Everett 802-257-5579

Newfane area

Newfane Courthouse 1825 (documents) Historic structure, Newfane center. Roof trusses sampled during repairs 1999 NCJ, NCC, NCT Hemlock (), spruce () Cutting date(s) 1824 (5), 1853 (1) Time-span of samples: 1579-1853 Contacts: Joan Marr

Pardon Kimball House 1832 (documents)

Residence in Newfane, sampled during repairs 2000 Wall studs, rafters. PKH Hemlock (5/5) Cutting dates ---Time-span of samples: 1589-1816 Contacts: Pam Baldwin, Four Columns Inn, Box 278, Newfane 05345 802-365-7713

Round Schoolhouse, Brookline 1822 (documents) Historic structure, Brookline. Sampled 20_? RSH Loose material, attic. Roof truss reportedly salvaged from local mill following flood. Not sampled. Hemlock (1/1) Cutting dates ---Time-span of samples: 1687 - 1819

Townshend Covered Bridge 1870 (documents) Historic structure, Newfane. Sampled 2000 Hewn truss. TCB Hemlock (4/9) Cutting dates 1868 (2), 1869 (1) Time-span of samples: 1703-1868

Windsor Vermont

Windsor Church 1846 (documents) 1846 – 48 Historic structure, Windsor town. Sampled 2001 Material from steeple repairs. WC Hemlock(11/11), spruce (1/1), yellow birch (4/4) Cutting dates 1845 (4),1846 (2), 1847 (2) Time-span of samples: 1592 – 1847 Contacts: Ted and Jane Hilles owners. Judy Hayward Historic Windsor 802-674-6752

Constitution House 17?? Documents Historic structure, Windsor town. Sampled 2002 CHW

White pine (/) Contacts: Judy Hayward

The Barn People, building recyclers Material from their scrap heap. Sampled 2002 TBP, LK Hemlock (7/), white pine (1/) Cutting dates Time-span of samples: 1511-1837 Contacts:

Ascutney Vermont

Ascutney Mountain, live tree cores. ATV Sampled 07/2002 Spruce 1851-2001 Yellow Birch (4/4 2 trees) 1839-2002

Redding Vermont

Dix farm barns 1799, 1868 Farm, Redding. Material salvaged from barns. RVB Spruce (13/15) Cutting dates 1798 (5), 1867 (2) Time-span of samples: 1581 - 1867

Mt. Holly Vermont

Forest Echo Farm 1879 Farm, Mt Holly. Wall studs, joists, wainscot. FEF Spruce, hemlock, ash Cutting dates 1878 (2), 1879 (2) Time-span of samples:

Tiny Mountain

Live tree cores. Sampled 1999 TMS Spruce, 1865-1999

Thetford Center Vermont

Noel Perrin farm 1835, 1860s Farm, Thetford. House, barn. Sampled 2004 Posts, attic. NPH, NPB Hemlock, white pine, red pine Cutting dates 1822 (1), 1834 (3), 1858 (1), 1862 (1), 1863 (1) Time-span of samples: 1551 - 1868 Contacts: Sara Coburn Box 312 Ryegate, Vt. 05042 svirginia@valley.net

Dover Vermont

Dover farm barn 1858 DHA Hemlock (4/4) Cutting date(s) 1856 (2), 1857 (1) Time-span of samples: 1631-1857

Vernon Vermont

Vernon chestnut barn 1865? VCB Dating tentative only Chestnut (7/10) 1781-1864 Contacts: Raphael Rosner Box 351, Marlboro 05344

Wilmington Vermont

Jason's house' siding 1823 Samples from Jason Breen salvaged from repair of local farmhouse. JHS Spruce siding Cutting dates 1823 Time-span of samples: 1579-1823

New Hampshire

New Boston, Richard Moody House 1788

Sampled April, 2015 by Jason Breen MH White pine (4/5), oak (2/2), chestnut (0/1) Cutting dates 1787 (6) Time-span of samples: 1682-1787 Contacts: Dick Moody 603-660-0393

New York City

Closet framing sampled 2005. DBJ ____Brownstone apartment 86th st? Hemlock (3/3) Cutting dates 1848 (1) Time-span of samples:

FORMAT:

Town Structure name, construction date (s) [noted if from documentation] Sample description, sampling date, IDs used on samples. Species common name (dated/sampled) Cutting dates (number) Time-span of dated samples